

Bay Window Specifications


- Made as individual blinds to fit in bay window
- Each section will have its own control and stacking option

Measuring Guides

Three-Sided Bay Window

Measure:

- A & C. Width of side windows from the corners to the point you would like the blind to cover.
- B. Width of the center blind from corner to corner.
- D. Width of baseline across front of bay from corner to corner.
- E. Depth from the center of the baseline to the back center window.



Five-Sided Bay Window

Measure:

- A-E. Same as three-sided bay window.
- F. Width of side window to side window corner (A).
- G. Width of side window to side window corner (C).
- H. Angle between windows (F) and (A).
- I. Angle between windows (A) and (B).
- J. Angle between windows (B) and (C).
- K. Angle between windows (C) and (G).

